Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE2179/1
Work Order Type: Weatherization
Audit Name: Audit (21)

CLIENT INFORMATION

Client Name: Settles, Pearlie Address:

Client ID: 50005DE2179 , TN

Alt. Client ID:

CLIENT CONTACT INFORMATION

Settles, Pearlie (901) 877-3937 Applicant/Person of

Record

Jr., Richard Settles (901) 412-2233 Other Contact for Applicant This is Mrs. Settles' Son

AGENCY INFORMATION

Agency: Delta Human Resource Agency Agency Phone: (901) 476-5226

Address: P. O. Box 634 **Fax:** (901) 476-5258

Covington, TN 38019 *Email Address:* Gloria.V.Williams@tn.gov

Agency Contact: Martin, Darrell L. Work Phone:

Cell Phone: (901) 262-8090

Email Address: DarrelllMartin@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Measures

Mea	sure 1 Crav	vl Space Door (28" x 33	")		Componen	ts			Inspected
Com	<i>ment</i> Replace	crawl space doors; 28"	k 33''						
					Estimated	<u>'</u>		Actual	
# Mat	terial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Oth	ner	Door Only- Material	Each	1					
2 Lab	oor	Labor		1					
3 Oth	ner	Unit- Material	Each	1					
4 Lab	oor	Labor		1					
Other	r Detail								
				Measur	e Sub Total:			Sub Total:	
Fiel	ld Notes:								
	asure 2 Crav	vI Space Door (32" x 19	")		Componen	ts			Inspected
		vl Space Door (32" x 19			Componen	ts		,	Inspected
		vI Space Door (32" x 19 crawl space doors; 32"			Componen Estimated			Actual	Inspected
Comi				Qty	-		Qty		Inspected
Comi	ment Replace terial / Labor	crawl space doors; 32"	x 19"		Estimated	1	Qty	Actual	
Comi	<i>ment</i> Replace <i>terial / Labor</i> ner	crawl space doors; 32" Description / Comment	x 19" <i>Units</i>	Qty	Estimated	1	Qty	Actual	
# Mat	ment Replace terial / Labor ner por	crawl space doors; 32" Description / Comment Door Only- Material	x 19" <i>Units</i>	Qty 1	Estimated	1	Qty	Actual	
# Mat 1 Oth 2 Lab	ment Replace terial / Labor ner por	crawl space doors; 32" Description / Comment Door Only- Material Labor	x 19" <i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
# Mate 1 Oth 2 Lab 3 Oth 4 Lab	ment Replace terial / Labor ner por	Description / Comment Door Only- Material Labor Unit- Material	x 19" <i>Units</i> Each	Qty 1 1 1	Estimated	1	Qty	Actual	
# Mate 1 Oth 2 Lab 3 Oth 4 Lab	ment Replace terial / Labor ner por	Description / Comment Door Only- Material Labor Unit- Material	x 19" <i>Units</i> Each	Qty 1 1 1	Estimated	1	Qty	Actual	
# Mate 1 Oth 2 Lab 3 Oth 4 Lab	ment Replace terial / Labor ner por	Description / Comment Door Only- Material Labor Unit- Material	x 19" <i>Units</i> Each	Qty 1 1 1	Estimated	1	Qty	Actual	
# Mate 1 Oth 2 Lab 3 Oth 4 Lab	ment Replace terial / Labor ner por	Description / Comment Door Only- Material Labor Unit- Material	v 19" Units Each Each	Qty 1 1 1 1	Estimated	1		Actual	
# Mat 1 Oth 2 Lab 3 Oth 4 Lab	ment Replace terial / Labor ner por	Description / Comment Door Only- Material Labor Unit- Material	v 19" Units Each Each	Qty 1 1 1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Mat 1 Oth 2 Lab 3 Oth 4 Lab	ment Replace terial / Labor ner por ner por ner	Description / Comment Door Only- Material Labor Unit- Material	v 19" Units Each Each	Qty 1 1 1 1	Estimated Unit Cost	1		Actual Unit Cost	
# Mat 1 Oth 2 Lab 3 Oth 4 Lab	ment Replace terial / Labor ner por ner por ner	Description / Comment Door Only- Material Labor Unit- Material	v 19" Units Each Each	Qty 1 1 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Client Name: Settles, Pearlie Client ID: 50005DE2179 Alt. Client ID: DOE Weatherization Assistant Version 8.5.0 Page 2 of 11

Report Run On: 5/24/2010

	atch a 2" x 19" area of wa tchen sink	ll under		Componen	ts		ı	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	Materials	Each	1					
2 Labor	Labor		1					
Other Detail								
] []		
			Measur	e Sub Total:		,	Sub Total:	
	atch a 8" x 24" area of wa ath vanity			Componen Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	Materials	Each	1					
2 Labor	Labor		1					
Other Detail						, , , , ,		
] []		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

WL	place (2) 32" x 22" Broke) # 4	en Panes i	n	Componer	its			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Material	Each	1					
2 Labor	Labor		1					
Other Detail				,				
			Measu	re Sub Total:			Sub Total:	
1	niace 24" x 26" Broken F	Pane in W	D #	Componer	nts			Inspected
Comment	place 24" x 26" Broken F	Pane in W	D #	Componer Estimated			Actual	Inspected
	place 24" x 26" Broken F Description / Comment	Pane in W Units	D#	•		Qty	Actual Unit Cost	
				Estimated	d	Qty		
# Material / Labor 1 Windows	Description / Comment	Units	Qty	Estimated	d	Qty		
# Material / Labor 1 Windows	Description / Comment Material	Units	Qty 1	Estimated	d	Qty		
# Material / Labor1 Windows2 Labor	Description / Comment Material	Units	Qty 1	Estimated	d	Qty		
# Material / Labor1 Windows2 Labor	Description / Comment Material	Units	Qty 1	Estimated	d	Qty		
# Material / Labor1 Windows2 Labor	Description / Comment Material	Units Each	Qty 1 1	Estimated	d			
# Material / Labor1 Windows2 Labor	Description / Comment Material	Units Each	Qty 1 1	Estimated Unit Cost	d		Unit Cost	

<i>Measure</i> 7 Rep	olace 31" x 47" Broken F	Pane in W	D #	Componen	its		ı	Inspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Material	Each	1					
2 Labor	Labor		1					
Other Detail						_		
			Measu	re Sub Total:]	Sub Total:	
Comment Seal ar	Itration Redctn ound all plumbing pipes unflatable chimney bladder			/				Inspected
				Estimated	<u>-</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail								
			Measu	re Sub Total:			Sub Total:	
Field Notes:								

Report Run On: 5/24/2010

Measure 9 D	WH Tank Insulation			Componen	ts		ı	Inspecte
Comment								
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Hot Water Equipment	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	WH Pipe Insulation			Componen				Inspecte
Comment	·	Unito		Estimated		044	Actual	
Comment # Material / Labor	WH Pipe Insulation Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty 1	-		Qty		Inspecte
Comment # Material / Labor 1 Insulation	Description / Comment		Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated			Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation	Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Measure 11 Atti	c Ins. R-19			Componen	ts A1		1	nspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-19	SqFt	1023					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Manager 42 Fla	or Inc. D. 40			Componen	40			nspected
Measure 12 Floo	or Ins. R-19			Componen	ts		1.	nspected
	or Ins. R-19			-				nspected
Comment	or Ins. R-19 Description / Comment	Units	Qty	Componen Estimated Unit Cost		Qty	Actual Unit Cost	nspected Total
Comment # Material / Labor		<i>Units</i> SqFt		Estimated		Qty	Actual	
Comment # Material / Labor	Description / Comment Floor Insulation -		Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -		Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -		Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -		Qty 1023	Estimated			Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -		Qty 1023	Estimated Unit Cost			Actual Unit Cost	
Comment # Material / Labor 1 Insulation Other Detail	Description / Comment Floor Insulation -		Qty 1023	Estimated Unit Cost			Actual Unit Cost	

	Measure 13 Stor	m Windows			Componen	ts WD11		1	nspected
C	omment								
					Estimated	·		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Storm Window	SqFt	12.75					
2	Labor	Storm Window	SqFt	12.75					
3	Other	Storm Window	Each Window	1					
c	Other Detail								
				Measure	Sub Total:			Sub Total:	
ſ	Field Notes:								
	Measure 14 CO I	Monitor is Needed			Componen	ts		I.	nspected
		Monitor is Needed			Componen Estimated			I Actual	nspected
C		Monitor is Needed Description / Comment	Units	Qty	-		Qty		nspected
<i>C</i>	omment	Description / Comment	<i>Units</i> Each		Estimated	,	Qty	Actual	
C # 1	Material / Labor Health and Safety	Description / Comment		Qty	Estimated	,	Qty	Actual	
c # 1	Material / Labor Health and Safety Items	Description / Comment CO monitor	Each	Qty 1	Estimated	,	Qty	Actual	
c # 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	,	Qty	Actual	
c # 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	,	Qty	Actual	
c # 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Hour	Qty 1 1	Estimated	,		Actual	
c # 1	Material / Labor Health and Safety Items Labor	Description / Comment CO monitor	Hour	Qty 1 1	Estimated Unit Cost	,		Actual Unit Cost	
c # 1	Material / Labor Health and Safety Items Labor Other Detail	Description / Comment CO monitor	Hour	Qty 1 1	Estimated Unit Cost	,		Actual Unit Cost	

Report Run On: 5/24/2010

1	Measure 15 Fix I	mproper venting (Cloth	nes Dryer)	Componen	is			Inspecte
C	omment Replace	Dryer Vent							
					Estimated			Actual	
¥	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	ther Detail								
Ĭ									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 16 Fix \	/entilation Inadequate ((Attic)		Componen	ts			Inspecte
	Measure 16 Fix \	/entilation Inadequate (ents (2)	(Attic)		Componen				Inspecte
C	omment Static Ve	ents (2)			Estimated		04:	Actual	
C #	omment Static Ve	ents (2) Description / Comment	Units	Qty	-		Qty		Inspecte
C #	omment Static Ve	ents (2)		Qty 1	Estimated		Qty	Actual	
<i>C</i>	omment Static Veneral / Labor Health and Safety	ents (2) Description / Comment	Units		Estimated		Qty	Actual	
C # 1	omment Static Venezation Material / Labor Health and Safety Items	Description / Comment Equipment	<i>Units</i> Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	1	Estimated		Qty	Actual	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	1	Estimated			Actual	
C # 1	Material / Labor Health and Safety Items Labor ther Detail	Description / Comment Equipment	Units Each Hour	1	Estimated Unit Cost			Actual Unit Cost	
C # 1	Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	1	Estimated Unit Cost			Actual Unit Cost	

	Measure 17 Fix V	Water Leak Present			Componen	ts		1	Inspected
C	omment Replace	2 traps under kitchen si	nk						
					Estimated	r		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
L									
	Measure 18 Insta	all vented chimney cover	er		Componen	ts		1	Inspected
		_	er		Componen Estimated			Actual	Inspected
С		_	er <i>Unit</i> s	Qty	•		Qty		Inspected Total
C #	omment Block ar	nd Seal Fireplace			Estimated		Qty	Actual	
C # 1	Comment Block an Material / Labor Health and Safety	nd Seal Fireplace Description / Comment	Units	Qty	Estimated		Qty	Actual	
C # 1	Comment Block and Material / Labor Health and Safety Items	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Comment Block and Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Comment Block and Material / Labor Health and Safety Items Labor	Description / Comment Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	Comment Block and Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	Qty 1 1	Estimated			Actual	
C # 1	Material / Labor Health and Safety Items Labor Other Detail	Description / Comment Equipment	Units Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
C # 1	Comment Block and Material / Labor Health and Safety Items Labor	Description / Comment Equipment	Units Each Hour	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

		or Barrier Needed sement/CrawIspace) Ap ⁻ t.	pox. 1023	3	Componen	ts			Inspected
C	comment Install gi								
					Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	SqFt	1					L
2	Labor	Labor		1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
			Work O	rder Gra	and Total:		Gran	d Total:	